



WEPAK
CORPORATION[®]

SUPERB

GENERAL INFORMATION

Specially formulated to emulsify grease, dissolve soil, and restore color. For rotary and dry foam machines.

DIRECTIONS

1. Vacuum carpet
2. Check for color fastness
3. Pre-spot
4. Dilute accordingly
5. Rake or sweep pile
6. When carpet is totally dry, vacuum again.

SPECIFICATIONS

Type.	Detergent
Color.	Clear
Physical State.	Liquid
Odor.	No odor
Specific Gravity.	0.93
Solubility (in water).	complete
Flammability (Flash Point).	None
pH.	7.0

MANUFACTURED BY

WEPAK
CORPORATION[®]

P.O. BOX 36803
CHARLOTTE, NC 28236
(704) 334-5781

CALL TOLL FREE
1(800)438-4270
FAX NUMBER
1(704)343-9757